



LAGUNA II ESPACE ESPACE IV VEL SATIS AVANTIME

See list on next page

fitted with G9T 702 - 710 - 712 - 742 engine

13B

TDC SENSOR

OTS: 0A99

MARK.: A5

Other sub-section concerned:

999

- Engine: **G9T 702 - 710 - 712 - 742**
- Gearbox: **XXX**

Basic manual: **XXX**

**The vehicle cut-offs are given as guidelines only,
before starting any work, it is ESSENTIAL to check that the vehicle is affected by
OTS 0A99**

• **Countries with PG&CS**

Network with ICM:

Refer to the list of OTS operations to be carried out in ICM.

Network without ICM:

If square **A5** on the blue marking label is not checked, and if the vehicle **is fitted with a G9T engine listed in the table on the following page**, contact your primary network to check in ICM.

• **Countries without PG&CS**

All networks:

If square **A5** is not checked on the blue marking label, and if the vehicle **is fitted with a G9T engine listed in the table on the following page**, the vehicle is affected.

LIST OF VEHICLES LIKELY TO BE AFFECTED

Vehicle	Type	from	to
LAGUNA II ESPACE	BG0 F	S 098430	S 490246
	JE0 K	K 002148	K 004528
		T 025725	T 999045
	JE0 S	K 004248	K 008343
ESPACE IV		T 008847	T 089762
	JK0 H	S 000037	S 017950
	KG0 F	S 048768	S 380123

Vehicle	Type	from	to
VEL SATIS	BJ0 E	S 011263	S 032905
	BJ0 F	S 000010	S 012201
	BJ0 G	S 000001	S 011701
	BJ0 M	S 011441	S 032906
AVANTIME	DE0 1	T 000001	T 001806

LIST OF ENGINES AFFECTED FOR THE AVANTIME

Engine	Suffix	from	to
G9T	712	C000001	C001503

TECHNICAL INFORMATION

Preventive operation

- Replace the TDC sensor, its mounting clip and the connector on the engine wiring harness.

Objective

- To prevent immobilisation of the vehicle.

Description of the operation

- Remove the engine undertray.
- Replace the TDC sensor (A) and its mounting clip (B) (Fig. 1).

IMPORTANT: the TDC sensor should slide freely in the clip when it is fitted.

- The TDC sensor **MUST** butt up to the flywheel (1) (Fig. 1).




Fig. 1

A - TDC sensor

B - Mounting clip

1 - Contact between the flywheel and the TDC sensor

- Replace the TDC sensor connector on the engine harness:
 - Remove the annealed sheath from the TDC connector wiring harness.
 - Cut the wire of track no. 1 at **120 mm (2) (Fig. 2)** from the rear of the TDC sensor connector.
 - Cut the wire of track no. 2 at **160 mm (3) (Fig. 2)** from the rear of the TDC sensor connector.

IMPORTANT: track allocations MUST be adhered to.

- Reconnect the sleeves of the new connector to the engine harness with a crimping tool.

- Shrink the sleeves with a hot air gun.
- Refit the annealed sheath.
- Reconnect the connector to the TDC sensor.
- Refit the engine undertray.

Marking the vehicle after work has been carried out

- Affix a blue label, **Part No.: 49 39 031 070**, to the driver's side front shock absorber turret.
Mark a cross in square **A5** using a marker pen.




Fig. 2

- 2 – length of track no. 1 wire on old connector: 120 mm
- 3 – length of track no. 2 wire on the old connector: 160 mm
- 4 – length of track no. 1 wire on new connector: 140 mm
- 5 – length of track no. 2 wire on new connector: 180 mm

DIESEL INJECTION

TDC sensor

13B

CLAIM COMPLETION AND CODING

When to take action

- The first time the vehicle visits the workshop.

Parts required

Quantity and description of parts		Part No.
1	Wiring kit	82 00 300 322
1	TDC sensor and clip kit	77 01 474 895

Tooling required

- Conventional.
- Crimping tool.
- Hot air gun.

Time required

Code	Description	Time
0096	Application of OTS	0.2
7522	Repair wiring harness	0.3
1971	Remove/refit TDC sensor	
	Laguna II, Avantime	0.3
	Espace	0.4
	Espace IV	0.5
	TOTAL	
	Laguna II, Avantime	0.8
	Espace	0.9
	Espace IV	1.0

Destination of removed parts

- **Other countries:** return to manufacturer.

Accounts procedure

- Request for reimbursement or individual claim, depending on the country.
- Nature of expense: **OTS**
- Expense code: **91**
- Parts at cost price.
- Labour at contractual warranty rate.
- Closure date: **31/12/2006**
- OTS code: 0A99**
(0 = Figure zero)